



## PUBLIC WORKS DEPARTMENT (B & R), HARYANA

OFFICE OF THE SUB DIVISIONAL ENGINEER  
PROVINCIAL SUB DIVISION NO.-4, GURUGRAM  
Email ID:- [sdepd4@gmail.com](mailto:sdepd4@gmail.com)



No:- 1143 Dated: 15/06/18


To

Mount Olympus School,  
Sector-47, Malibu Towne,  
Gurugram (Haryana).

**Subject: - Structure stability certificate.**

**Reference:** Your letter no.MOS/2018-2019 Dated 15.06.2018.

The site has been inspected by the undersigned alongwith J.E. incharge on 15.06.2018. From physical inspection, the building is found safe. So far as structural design is concerned, Sh. B.K. Singh C/o ABL Structure Consultants Pvt. Ltd., Pitam Pura, Delhi-110034 Structural Consultant is responsible for the same as per Structural Stability certificate given by him on dated 21.08.2015.

  
Sub Divisional Engineer  
Provincial Sub Division No. 4,  
P.W.D. Haryana, Gurugram

  
Principal  
Mount Olympus School  
Sector-47, Malibu Towne  
Gurugram

